

Follow-Up of Newport Kappa Diffractometer Incident at 7ID-C

Don Walko, MHATT-CAT
Sector 7, XOR, APS, ANL
d-walko@anl.gov



Presentation for APS Technical Working Group, 1/22/04

For further info, see

http://www.mhatt.aps.anl.gov/~walko/kappa_damage

Reminder of the source of damage:

Y1 jack failed & diffractometer fell. Fundamental problem was weak retaining nut, which split in two (in addition to issue of cross-roller bearing cage migration).




What Newport has offered:

- Repair damage to base
 - return to original condition at Newport's expense
- Redesigned jack, using rail & carriage for slides with recirculating balls
 - we pay for this (roughly at cost)
 - available for other kappa instruments at APS
- Thick safety plate on top of slide (just in case)
- Thicker, better-secured retaining nut


Improved slides

front view




thick top plate

bottom view




new retaining
nut: steel,
11mm thick,
now held with
three screws

Max stress=145 Mpa
cf yield stress= 500 MPa



Max deformation=5.9um



Dismantling of kappa and shipping of base

